
WIRING INSTRUCTIONS



WIRING SPECIFICATIONS								
Wire No.	Wire Color	Origin or Part No.	Gauge	Length	Terminals, Connectors and End Wire Preparation			
_ 1	Blue	Cord	16	2.5*	Strip .25" for C1.			
2	Brown	Cord	16	2.5"	Strip .25" for C1.			
3	Red	Field	16	7"	Strip .20" for T4.			
4	Red	Field	16	10"	Strip .25" and tin for C2.			
5	Yellow	Field	16	1.5"	Strip .18" for T1.			
6	Black	Field	16	1.5"	Strip .18" for T1.			
7	Black	Module	18	6"	Strip .25" and tin.			
8	Black	Module	18	6*	Strip .16" for T2.			
9	Blue	Module	18	6.37"	Strip .20* for T3.			
10	Black	Suppressor		1"	Strip .25" for C1.			
11	Black	Suppressor		1.75"	Strip .25" for C2.			
12	Black	23-94-6245	18	3.25*	Strip .375" and tin for switch / Strip .25" for C1.			
13	Black	23-94-6245	18	3.25*	Strip .375" and tin for switch / Strip .25" for C1.			
14	Red	23-94-6070	18	3.75"	Strip .375" and tin for switch / Strip .25" for C2.			

All leads must be held to ± 1/8".
All lead lengths are before stripping.

TERMINAL DESCRIPTION					
Code	Onty.				
T1	23-74-0750	2			
T2	23-74-1060	1			
ТЗ	23-74-0440	1			
T4	23-74-0970	1			
		l			

CONNECTOR DESCRIPTION					
Code	Part No.	Qnty.			
C1	22-56-0451	1			
C2	22-56-0456	1			