
WIRING INSTRUCTIONS



WIRING SPECIFICATIONS								
Wire No.	Wire Color	Origin or Part No.	Ga.	Length	Terminals, Connectors an	nd End Wire Preparation		
1a	Black	14-20-1090	18	3.7	Component of remote dial assy. / Strip .19 for T4.			
1b	Black	14-20-1090	18	7.25	Component of remote dial assy.			
1c	Black	14-20-1090	18	7.0	Component of remote dia	remote dial assy. / Strip .32 and tin.		
1d	Black	14-20-1090	18	10.3	Component of remote dial assy. / Strip .19 for T3.			
2a	Black	22-56-0700	16		Component of the blade housing assembly.			
2b	White	22-56-0700	16		Component of the blade housing assembly.			
3a	White	23-94-7400	18	3.13	Strip one end .19 for T2.	Chair both 45 and inia for T4		
3b	White	23-94-7400	18	4.4	Strip one end .15 for T1.	Strip both .15 and join for T1.		
4a	Black	23-94-7405	18	2.05	Strip one end .19 for T4.	Out hath 45 and take for T4		
4b	Black	23-94-7405	18	4.4	Strip one end .15 for T1.	Strip both .15 and join for T1.		
5	Black	23-94-7410	18	3.0	Strip each end .19 for T2 and T5.			
6	White	23-94-7415	18	7.25	Strip one end .32 and tin. / Strip other end .19 for T4.			

BULK LEAD WIRE - BULLETIN 58-01-0003

NOTE:All leads must be held to ± 1/8". All lead lengths are before stripping.

TERMINAL DESCRIPTION							
Code	ode Part No.						
T1	23-74-1060	4					
T2	23-74-0750	2					
Т3	23-74-0900	1					
T4	23-74-0605	3					
T5	23-74-0017	1					